WAC LIGHTING Responsible Lighting®

SK18, SK24, SK36, SK48

## NOTE: Canopy and rods are packaged separately.

## CAUTION:

Always turn off power at fuse box prior to installation to prevent electrical shock. For installation by a qualified electrician.

## NON POWER END OF TRACK

- 1. Secure cross bar (SK1) up against ceiling.
- 2. Push extension rod (R18-R48) through the canopy plate (SK3) and tighten by screwing to the cross bar.
- 3. Attach the other end of the extension rod to the track clamp (SK4) with nut (P3).
- 4. Open the mouth of the clamp and insert the track into the clamp, and tighten it with cap nuts and threaded rods (SK6 and SK5)

## **POWER END OF TRACK**

Install over a standard 4-inch junction box.

- 1. Attach cross bar (SK1) to the outlet box. With wire nuts (P7), connect the extension wires (not included) with the incoming wire in the outlet box.
- 2. Thread wire through the center opening of the cross bar and canopy plate to the extension rod (R18-R48).
- 3. Push extension rod up against the canopy plate and tighten by screwing into the cross bar.
- 4. Tighten the other end of the extension rod into the track clamp (SK4) with R1.
- 5. Complete wire connections with live end through the knockout of the live end.
- 6. Close live end and insert live end into the track clamp (SK4).
- 7. Tighten track clamp (SK4) with cap nuts and threaded rods (SK6 and SK5).



**WAC Lighting** www.waclighting.com Phone (800) 526.2588 • Fax (800) 526.2585 Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050 **Western Distribution Center** 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585