


WYNDHAM COLLECTION



REQUIRED TOOLS NOT IN BOX



Electric drill




Tape measure



Drill bit ($\phi 8$)




Pencil




Screwdriver

INSTALLATION INSTRUCTIONS


1



2



3



WC-R4100-MIR-58
INSTALLATION