

















NAN-WK-105-GG




IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.

PART


(A)  x1	(B)  x1	(C)  x1
(D)  x1	(E)  x1	(F)  x4
(G)  x2	(H)  x2	(I)  x2
(J)  x2	(K)  x1	(L)  x4
(M)  x1	(N)  x1	(O)  x2
(P)  x4		

PARTS		
 ①	 12PCS	 ⑧ M6x40 8PCS
 ②	8PCS	 ⑨ M6x25 4PCS
 ③	M6X30 12PCS	 ⑩ M6X20 8PCS
 ④	M4X14 20PCS	 ⑪ M5x55 8PCS
 ⑤	4PCS	 ⑫ M6x12 8PCS
 ⑥	M8 4PCS	 ⑬ 1SET
 ⑦	M6x35 4PCS	 ⑭ M5x70 4PCS
1	 ③ X4 ④ X16 ⑤ X4	
2	 ① X4 ② X4	

3





X2




6 X2
7 X2
10 X2
11 X2

4



8 X8
11 X4
14 X4


5



1 x 8



2 x 4

6



3 x 8


7



9 X4


10 X4

8



12 X8

9



4 X4

10

