




# *Boraam Industries*

## **JONES SWIVEL STOOL**

ASSEMBLY INSTRUCTIONS





**PLEASE READ ME FIRST**



- Have questions about assembling your item?



- Item or parts damaged?



- Missing a part?



- We're here to help!




(847)949-6300 (M-F, 9am-5pm CST)




[www.boraamindustries.com](http://www.boraamindustries.com)




[customerservice@boraamindustries.com](mailto:customerservice@boraamindustries.com)




22 PCS  
Ø6x10




2 PCS  
Ø6x13




26 PCS  
Ø6x16




2 PCS  
Ø7.5x15.5




4 PCS  
M6x35




12 PCS  
M6x40




6 PCS  
M6x45



2 PCS  
M6x50




4 PCS  
M6x60




1 PC


1




2




3




4




5







6



7







# 01



DO NOT TIGHTEN BOLT COMPLETELY.



# 02



TIGHTEN BOLT COMPLETELY.




# 03

<b>A</b>  6 PCS	<b>C</b>  6 PCS	<b>G</b>  2 PCS	<b>I</b>  4 PCS
--	--	--	--





TIGHTEN BOLT COMPLETELY.


# 04





TIGHTEN BOLT COMPLETELY.

# 05

<b>A</b> 	<b>B</b> 	<b>C</b> 	<b>D</b> 	<b>G</b> 	<b>H</b> 
4 PCS	2 PCS	4 PCS	2 PCS	4 PCS	2 PCS



TIGHTEN BOLT COMPLETELY.



BE SURE TO CHECK ALL BOLTS ARE SECURELY  
TIGHTENED PRIOR USING THIS STOOL.