



PARTS SET-UP SHEET				DATE	01/04/18		BY	Samuel Turner				
PARENT SKU	B700			BIN LOC			PRD CD			WT	NMFC	
KEYWORD	NOVA			PARTS			0			1	100	
EXD=ENTER IN EXTENDED DESCRIPTION				"NEW ITEMS: M/M Freeze Date - 8 Months								
PART SKU	DESCRIPTION			LOC	NON-STOCK	MATERIAL	HTS #	COST	VEND #	MIN	MAX	NOTES
PB700-24SUPPORT	Support Rail			100		Made by Plywood			V11004			Support rail of Mirror
PB700-24HDWR	For mirror assembly Mirror to Dresser			100		Allen Bolt 1/4" x1-1/2"(L) (8) Flat Washer 1/4" (8) Lock Washer 1/4"(8) Allen Wrench 1/6"(1)			V11004			For mirror assembly Mirror to Dresser
PB700-DWRGLD	Common part use for all case B700-01/04/05/E700-01/T700-00/01/02			100		Metal			V11004			Ball bearing glide for drawer(6set)
PB700-HANDLE	Common part use for all case B700-01/04/05/E700-01/T700-00/01/02			100		Metal			V11004			Assembly to Drawer front & including screws
PB700-01SUPPORTLEG	Including adjustable leverler			100		Wood			V11004			
PB700-01BASE	Including adjustable leverler			100		ELECTRIC			V11004			
Pictures for Refrence ONLY (Below)				B700-01 *below								
												
Pictures for Refrence ONLY (Below)				B700-01 AI INSTRUCTIONS *below								



Emerald Home Furnishings
www.emeraldhome.com

Emerald Home Furnishings

ASSEMBLY INSTRUCTION

Item No:B700-01 6 DRAWER DRESSER-STERLING FINISH SET UP


Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts that may have come loose inside the carton during shipment.

Before you Assemble : Please read all instructions carefully before beginning the assembly process. It is recommended that 2 people work together during assembly to prevent personal injury and to ensure that heavy or cumbersome parts are not damaged during the process.

CAUTION: For your safety, this product requires two people to lift.

★ Remark : there is a tip restraint kit provided on the back of this product. Please read the directions thoroughly and install immediately when placed in home.

Anti Tipping Hardware



[illegible]