



















A  Φ 8x40MM 28 pcs	B  46 pcs	C  Φ 3.5x14MM 86pcs
D  Φ 3*35MM 10 pcs	E  2 pcs	F  2 pcs
G  16 pcs	H  6 pcs	J  6 pcs
K  894MM 1 pcs	L  1435MM 1 pcs	M  46 pcs
N  2 pcs	O  4 pcs	




STEP 1



B1x2pcs

STEP 2



B1x6pcs




Cx1pc




Fx1pc

STEP 3




	B1x6pcs		Cx1pc		Fx1pc
--	---------	---	-------	---	-------


STEP 4




	Ax2pcs		B2x6pcs
--	--------	---	---------


STEP 5




	Ax2pcs		B2x6pcs
--	--------	---	---------

STEP 6




	Ax2pcs		B2x2pcs
--	--------	---	---------

STEP 7




 B1x12pcs


STEP 8




 B1x4pcs

STEP 9



	Ax6pcs		B2x6pcs
--	--------	---	---------


STEP 10






Lx1pcs

STEP 11



	Ax4pcs		B2x4pcs
--	--------	---	---------

STEP 12




Cx6pcs



E1x2pcs

STEP 13





Cx6pcs




E1x2pcs

STEP 14




	Ax6pcs		B2x6pcs
--	--------	---	---------

STEP 15



STEP 16



B1x6pcs




Cx12pcs




Ox4pcs

STEP 17




	Ax6pcs		B2x6pcs
--	--------	---	---------

STEP 18




	Gx16pcs		Cx16pcs
--	---------	---	---------

STEP 19



Kx1pcs

STEP 20



Cx12pcs






Hx2pcs






Jx6pcs

STEP 21





Cx24pcs

STEP 22





B1x10pcs

STEP 23





B2x10pcs

STEP 24




STEP 25



Dx10pcs

STEP 26




Cx8pcs





E2x2pcs

STEP 27




Hx4pcs

STEP 28








In order to make the product more beautiful, please paste hardware M on the exposed holes



Mx46pcs

STEP 29



  Nx2pcs

