



















A  Φ8x40MM 32 pcs	B  50 pcs	C  Φ3.5x14MM 115pcs
D  Φ3*35MM 10 pcs	E  2 pcs	F  2 pcs
G  24 pcs	H  7 pcs	J  9 pcs
K  854MM 1 pcs	L  1435MM 1 pcs	M  50 pcs
N  2 pcs	O  5 pcs	P  12 pcs




STEP 1



	B1x6pcs
	Cx1pc


	Fx1pc		Px6pc
---	-------	---	-------

STEP 2




	B1x6pcs		Cx1pc		Fx1pc
--	---------	---	-------	---	-------

STEP 3



B1x2pcs

STEP 4




Ax2pcs





B2x6pcs

STEP 5



	Ax2pcs		B2x6pcs
--	--------	---	---------

STEP 6




Ax2pcs




B2x2pcs

STEP 7




Px6pcs

STEP 8




B1x14pcs

STEP 9





	Ax8pcs		B2x8pcs
--	--------	---	---------

STEP 10




Lx1pcs

STEP 11



Ax6pcs




B1x6pcs



B2x6pcs

STEP 12




Cx6pcs



E1x2pcs

STEP 13




Cx6pcs




E1x2pcs

STEP 14




	Ax6pcs		B2x6pcs
--	--------	---	---------

STEP 15



STEP 16



B1x6pcs





Cx15pcs




0x5pcs

STEP 17




	Ax6pcs		B2x6pcs
--	--------	---	---------

STEP 18




	Gx24pcs		Cx24pcs
--	---------	---	---------

STEP 19




 Kx1pcs

STEP 20



STEP 21



Cx18pcs






Hx3pcs




Jx9pcs

STEP 22




Cx36pcs

STEP 23





	B1x10pcs
--	----------

STEP 24





	B2x10pcs
--	----------


STEP 25



STEP 26



STEP 27




Cx8pcs





E2x2pcs

STEP 28



Hx4pcs

STEP 29









In order to make the product more beautiful, please paste hardware M on the exposed holes



Mx50pcs

STEP 30



 Nx2pcs

