



UTTERMOST

Assembly Instruction


STYLE: 24410

Parts list

A	TABLE TOP	1PC
B	TABLE LEG	1PC

Hardware list

ALLEN WRENCH	1PC
ALLEN HEAD BOLT	3PCS



1. Take the parts carefully out of the carton, and place it on a flat surface, make sure that the parts will not be damaged.

2. Place the Table Top (A) upside down on flat and soft surface, and then insert the 3 holes in the legs part(B) into the allen head bolts which has been weld in the back side of table top(A). Allen Wrench is used here.

To Clean, wipe with soft dry cloth.