


Assembly Instruction Item No: BOC-370

Description: CORNER TABLE


Rev 2 :2021-11-05





Item No: BOC-257T
Description: LIFT DESK TOP & BASE LIFT#200WHT

Rev 2 :2021-11-05






Item No: BOC-257T Description: LIFT DESK TOP

Rev 2 :2021-11-05

Use the screws of the lifting base to attach the base to the top bottom through the predrilled holes. follow the instruction of lifting base to install all the other components and fix the cables with cable clips.






Item No: BOC-370 Description: CORNER TABLE


Rev 2 :2021-11-05

HARDWARE LIST


No	Description	Sketch	Q'TY
Α	Allen wrench 5mm		1PC
В	Bolt Ø 5/16"x2"	0	2PCS
С	Lock washer Ø5/16"x12mm	U	2PCS
D	Flat washer Ø5/16"x19mm	0	2PCS
Е	Allen wrench 4mm		1PC
F	Bolt Ø 1/4"x1-1/2"	0	5PCS
G	Bolt Ø 1/4"x3/4"	0	8PCS
Н	Lock washer Ø1/4"x12mm	Ú	13PCS
I	Flat washer Ø1/4"x19mm	0	13PCS
J	Long metal bracket	/	1PC
K	Short metal bracket		1PC

PARTS LIST






To set up a left corner table, please match the "L" label on the apron to the "L" label found underneath the corner table's top. to set up a right corner table, please match the "R" label on the apron to the "R" label found underneath the corner table's top.





Item No: BOC-370
Description: CORNER TABLE

Rev 2 :2021-11-05



Configuration for BOC-370, BOC-357D & BOC-347D assembing together.




Item No: BOC-347C
Description: 48IN. CREDENZA


HARDWARE LIST

No	Description	Sketch	Q'TY
А	File rods 498mm x Ø7		2PCS



HARDWARE





Assembly Instruction Item NO: BOC-347H

6/10

Hardwares

NO	Description	Sketch	Q'TY
A	Touch up Pen	P	1pc

