

PARTS AND HARDWARE.

PARTS LIST

No.	DESCRIPTION	IMAGE	Q'TY
P1	SEAT		1
P2	METAL LEGS		2
P 3	METAL LEGS	V	2
P 4	METAL LEGS	all all a	1

HARDWARE LIST

No.	DESCRIPTION	IMAGE	Q'TY
H1	BOLT (6X16MM)	()mm)	4
H2	SPRING WASHER (6X10X1MM)	0	8
НЗ	FLAT WASHER (6X14X1.5MM)	0	8
H4	ALLEN KEY	L.	1
H5	BOLT (6X13MM)	Dana	4
H6	BOLT (6X25MM)		4

NOTES.

Thank you for purchasing this quality product! Be sure to check all packing material carefully for small part that may have come loose inside the carton during shipping.

CAUTION: Ensure not to overtighten screws to reduce the risk of stripping or breakage.



STEP 3.





STEP 4.

