

WYNDHAM COIFCTION












PACKING LIST












INSTALLATION AND ADJUSTMENT OF HINGES











REQUIRED TOOLS NOT IN BOX















Tape measure Pencil Electric Drill


Drill Phillips Screw


Phillips Screwdriver Adjustable Wrench


Spirit Level

Silicone sealant

INSTALLATION INSTRUCTIONS







WC-CG8000-48 INSTALLATION