

WYNN PULL OUT TABLE

Assembly instructions:

PART LISTS

NO.	DESCRIPTION	IMAGE	Q'TY
P1	TABLE TOP		1PC
P2	METAL BASE		1PC
Р3	METAL BASE SIDE	7	2PCS
P4	METAL BASE FRONT		1PC

HARDWARE LISTS

NO.	DESCRIPTION	IMAGE	Q'TY
H1	BOLT	@	10PCS
H2	SPRING WASHER 1/4"	0	10PCS
НЗ	FLAT WASHER 1/4"	0	10PCS
H4	ALLEN KEY	J	1PC

NOTE: PO# is located underneath/ inside of each item. Please be prepared to provide this # should any claim be necessary.

CAUTION: Item is heavy assembly should be performed by two people.

Estimate assenbly time:5 minutes

