




















A  $\Phi 8 \times 40 \text{MM}$ 40 pcs	B  63 pcs	C  $\Phi 3.5 \times 14 \text{MM}$ 156 pcs
D  $\Phi 3 \times 35 \text{MM}$ 15 pcs	E  3 pcs	F  4 pcs
G  32 pcs	H  10 pcs	J  12 pcs
K  1 pcs	L  1435MM 2 pcs	M  63 pcs
N  2 pcs	O  6 pcs	P  16 pcs




STEP 1



	B1x6pcs
	Cx1pc


	Fx1pc		Px6pc
---	-------	---	-------


STEP 2




	B1x2pcs
--	---------





STEP 3





	Ax2pcs		B2x6pcs
--	--------	---	---------

STEP 4



	B1x6pcs				
	Cx2pc		Fx2pc		Px2pc

STEP 5




Ax2pcs




B2x6pcs


STEP 6




	Ax2pcs		B2x2pcs
--	--------	---	---------

STEP 7





	Cx1pc		Fx1pc		Px2pc
--	-------	---	-------	---	-------

STEP 8





	Px6pcs
--	--------

STEP 9




B1x18pcs




B1x8pcs

STEP 10




	Ax10pcs		B2x10pcs
--	---------	---	----------

STEP 11




Lx2pcs

STEP 12



	Ax8pcs		B2x8pcs
--	--------	---	---------

STEP 13




Cx6pcs



E1x2pcs

STEP 14





Cx12pcs



E1x4pcs

STEP 15




Ax8pcs





B2x8pcs

STEP 16




STEP 17




	B1x8pcs		Cx18pcs		0x6pcs
--	---------	---	---------	---	--------

STEP 18




	Ax8pcs		B2x8pcs
--	--------	---	---------

STEP 19




	Gx32pcs		Cx32pcs
--	---------	---	---------

STEP 20




	K1x1pcs		K2x1pcs
--	---------	---	---------

STEP 21






STEP 22




	Cx24pcs		Hx4pcs		Jx12pcs
--	---------	---	--------	--	---------


STEP 23




Cx48pcs

STEP 24




 B1x15pcs

STEP 25





 B2x15pcs

STEP 26






STEP 27



Dx15pcs

STEP 28




Cx12pcs




E2x3pcs

STEP 29




Hx6pcs






STEP 30




In order to make the product more beautiful, please paste hardware M on the exposed holes

 Mx63pcs

STEP 31



 Nx2pcs

