MM-SW10004 Assembly Instruction

FITTINGS COMPONENT PARTS (A) (mm) X4 X4 (B) 01 \bigcirc X4 COMPONENT CHECKLIST 02 PART Qty. No. Seat 01 1 02 Leg TOOLS REQUIRED (C) = 1 © : B © = B = A | Allen key(supplied)