





CPM5274-FS-HA




CPM5274-FS-HA



A x12
Spec: $\phi 10 \times L40$



B x12
Spec: M8*L95



C x12
Spec:



D x12
Spec: M8



E x12
Spec: $\phi 40$



F x12
Spec: 5/16*L35




G x18
Spec: $\phi 8 \times \phi 18$



H x12
Spec: $\phi 8 \times \phi 14$




I x1
Spec: 5#



J x2
Spec: 5/16*L60




K x1
Spec: 10g



L x16
Spec: M6*45




M x2
Spec: L180



N x1
Spec: 14#



O x2
Spec: $\phi 8 \times 30$




P x4
Spec: $\phi 7 \times L30$




Q x4
Spec: $\phi 15 \times H12$




R x16
Spec:




2






3


4







5

6






7



8



9

10

