




INSTALLATION PROCEDURE




MEASURE THE DISTANCE
BETWEEN TWO POINTS

①




PUNCH HOLES IN THE MEASURED
POINTS AND DRIVE THE SCREWS

②






INSTALL Z-BAR

③



④



ACCURATELY
CONNECT WALL
WIRING