



NAN-CD-22181-GG




IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.

A X2	B X1	C X1	D X2
E X4	F X1	G X2	H X1
① M6x30 X16	② M6x12 X6	③ X1	④ X11
⑤ M8 X8	 		


1



2



3



4

