



# WF192607

















## NOTICE:



Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts, which may have come loose inside carton during shipment. Identify and count all parts and compare with the parts list below.



If the item is arrived damaged or any other problems, please be sure to attach the order number and the picture showing the matter, contact our official E-mail address: [Csr@merax.com](mailto:Csr@merax.com), We will provide a prompt resolution at the earliest convenience. Thank you for your understanding and cooperation.




A	*22	B	X22	C	X22	D	X10	E	X1	F	*4	G	*4
													
φ 6X35		φ 15X12		φ 7. 8X30		φ 7X47		M4X55		340mm		340mm	
H	*34	I	*8	J	*6	K	*16	L	*4	M	*2	N	*3
													
3. 5*14mm		4*35mm		M6*25mm		M6*12mm		ø5*13mm					


# STEP: 1




H	*8	G	*4
			
3.5*14mm		340mm	



# STEP: 2





A	*14
	
Φ 6X35	



# STEP: 3




B	X4	C	X4
			
$\phi$ 15X12		$\phi$ 7. 8X30	





# STEP: 4




B	X2	C	X1
			
$\phi$ 15X12		$\phi$ 7. 8X30	



STEP: 5




D	X2	E	X1	B	X4	C	X5
							
$\phi$ 7X47		M4X55		$\phi$ 15X12		$\phi$ 7. 8X30	

STEP: 6






B	X4	C	X4
			
$\phi$ 15X12		$\phi$ 7. 8X30	

# STEP: 7






# STEP: 8




D	X8	C	X8
			
Φ 7X47		Φ 7. 8X30	



# STEP: 9





J	*4	K	*8
			
M6*25mm		M6*12mm	




# STEP: 10





J	*2	K	*8
			
M6*25mm		M6*12mm	



# STEP: 11



N	*1	H	*6	M	*2
					
		3. 5*14mm			


# STEP: 12




H	*8	L	*4
			
3. 5*14mm		ø 5*13mm	



# STEP: 13








# STEP: 14




N	*2	H	*4	A	*8
		3. 5*14mm		φ 6X35	





# STEP: 15




F	*2	H	*4	I	X4	B	X4
							
340mm		3. 5*14mm		4*35mm		φ 15X12	

# STEP: 16



F	*2	H	*4	I	X4	B	X4
							
340mm		3. 5*14mm		4*35mm		φ 15X12	

# STEP: 17



# STEP: 18

