



ASSEMBLY INSTRUCTIONS OF BRUX CONSOLE 2 DRAWERS


1




2



3




4



Hexa Bolt M8X50=8 PCS



Washer M8X50=8 PCS



Wrench No 12
(Not Included)