


Tools Required: Flathand screwchter, Philips screwditer, plans, who cutters, who adopters, electrical laps, salely glass Japit Source: (3) E12 Bass Bals 60V Machami(Not Indude). Editended Assembly Time: 15-30 minutes

reparation: Identify and inspect all parts batters baginning installation. Check package content list and dilagrams below to be sure all parts are resent. If any parts are missing or demograf, do not attempt to assemble, install, or operate the ficture. Context customer service for replacement <u>arts.</u>

## ▲ Warnings and Cautions Turn of sections at circuit breaker or

Turn off electricity at circuit breater or main fuse box before installation. Consult a licensed electrician if in doubt. These instructions are provided for your eatiety. It is very important you read them completely before installing the fixture. We storaply recommend that a ficensed, professional electrician perform the installation.

Disconnect fixture from power source before replacing builbs. Make sure builbs are given sufficient time to cool before removal.






Figure 1

2 of 2