



3



2 X10


4 X6

4



5 X8


1



1 X6








3 X4

2



1 X5


3 X2

Ⓐ  X1	Ⓑ  X1	Ⓒ  X3
Ⓓ  X3	Ⓔ  X1	Ⓕ  X1
Ⓖ  X2	Ⓖ  X1	

PARTS

①	11	M6X35MM	
②	10	M6X30MM	
③	6	M6X12MM	
④	6		
⑤	8	M6X25MM	

NAN-WK-110-GG



IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.