



ASSEMBLY INSTRUCTION




Hardware List


① x 1




② x 1




③ x 1




④ x 1




⑤ x 1




⑥ x 1




⑦ x 1




⑧ x 1



⑨ x 2




⑩ x 1




Hardware List


11 x 1




12 x 1




13 x 1




14 x 1



15 x 1



16 x 4



17 x 4




18 x 8




19 x 12




20 x 12



21 x 4




22 x 16



Hardware List

23 x 12



24 x 1



25 x 8



26 x 8




27 x 8




28 x 1




step 1




step 2




step 3




step 4




step 5




step 6




step 7




step 8




step 9




step 10




step 11



step 12



step 13



step 14

