


Item No: BOC-257T
Description: LIFT DESK TOP & BASE LIFT#200WHT

Rev 2 :2021-11-05






Item No: BOC-257T Description: LIFT DESK TOP

Rev 2 :2021-11-05

Use the screws of the lifting base to attach the base to the top bottom through the predrilled holes. follow the instruction of lifting base to install all the other components and fix the cables with cable clips.






Item No: BOC-347D Description: DESK


Rev 2 :2021-11-05

#### **HARDWARE LIST**

No	Description	Sketch	Q'TY
Α	Allen wrench 5mm		1PC
В	Bolt Ø 5/16"x2-1/2"	0	8PCS
С	Lock washer Ø5/16"x12mm	U	8PCS
D	Flat washer Ø5/16"x19mm	0	8PCS

#### PARTS LIST








Item No: BOC-370 Description: CORNER TABLE


Rev 2 :2021-11-05

#### **HARDWARE LIST**


No	Description	Sketch	Q'TY
Α	Allen wrench 5mm		1PC
В	Bolt Ø 5/16"x2"	0	2PCS
С	Lock washer Ø5/16"x12mm	U	2PCS
D	Flat washer Ø5/16"x19mm	0	2PCS
Е	Allen wrench 4mm		1PC
F	Bolt Ø 1/4"x1-1/2"	0	5PCS
G	Bolt Ø 1/4"x3/4"	0	8PCS
Н	Lock washer Ø1/4"x12mm	Ú	13PCS
I	Flat washer Ø1/4"x19mm	0	13PCS
J	Long metal bracket	/	1PC
K	Short metal bracket		1PC

#### PARTS LIST






To set up a left corner table, please match the "L" label on the apron to the "L" label found underneath the corner table's top. to set up a right corner table, please match the "R" label on the apron to the "R" label found underneath the corner table's top.





Item No: BOC-370
Description: CORNER TABLE

Rev 2 :2021-11-05



Configuration for BOC-370, BOC-357D & BOC-347D assembing together.