

ASSEMBLY INSTRUCTION


WX16225

COMPONENTS LIST


① Top Board x 1




② Board W/Small Hole



③ Board W/Large Hole



④ Bottom Board x 1



⑤ Steel Pin x 12



⑥ Metal Cam x 12



⑦ Wood Dowel x 4





⑧ 1" Screw x 4





⑨ Fabric Cushion x 4





STEP 1





STEP 2



STEP 3




STEP 4




For missing parts or replacement , you may contact your merchant or its distribution center(Ph: 714-288-2005, Email:promanproducts@hotmail.com).
For any other questions, please contact Customer Service Department of the merchant from where you placed your order.

STEP 5




⑤ x 2	
⑥ x 2	

STEP 6




⑤ x 2	
⑥ x 2	

STEP 7



⑧ x 4	
⑦ x 4	

STEP 8



Completed

⑨ x 4	
-------	--