
## **ASSEMBLY INSTRUCTION**



1. Place all parts on a clean soft surface.Make sure you have all parts and hardware as identified on the part list.

2. Lay the table top(A) on a flat, non-abrasive surface. Attach table legs(B) to table top by using bolts(D) and washers(E).Do not tighten all bolts.

3. Reverse the table top upright position. Tighten all bolts (Do not over tighten) and cover them with the bolt caps(F). Now your table is ready for using.

✗ DO NOT OVER TIGHTEN

✗ NO SOCKET DRIVERS



🔆 NO POWER TOOLS



## **ASSEMBLY INSTRUCTION**

ATTENTION: 1. Please read these instructions carefully before assembly. 2. Aluminum is soft metal, over tighten may strip thread or break the part. 3. DO NOT use power tools.									c ≤ □ <b>0</b>	(M8*40)
List of Parts for Assembly								V//	F	6
	Parts Description	Qty	No	Parts Description	Qty				E	0
Α	Chair Frame	1	ĸ	Foot Cap	6			N/	F	Ð
В	Chair Base	1	L	Seat Cushion	1			<b>N M</b>		
С	METAL PLATE	4	М	Back Cushion	1			4	G	
D	Bolt(M8*40)	4								
E	WASHER	4				•			Н	
F	SPRING WASHER	4								-
G	NUT	4							Ι	$\Theta$
н	BOLT CAP	4					K			
I	NUT CAP	4					2040-CG		J	
J	WHENCH	2					2040-00	ļ		

