



ASSEMBLY INSTRUCTION


Combination 2




Combination 1




Hardware List




① x2




② x2




③ x2



④ x2




⑤ x6



⑥ x2

⑦ x16



⑧ x16



⑨ x24



⑩ x2




⑪ x16




⑫ x16




Tip Restraint Kit




a x4



b x4




c x2




d x2

Step 1




X2

Step 2




X2

Step 3




X2

Step 4




X2

Step 5




X2

Step 6




X2

Step 7



X2



X2

Step 8

