



Assembly Instruction

A	X28	B	X28	C	X8	D	X8	E	X1	F	X8	G	X8
M6x35mm		Ø15x12mm				M3x14mm		4mm		M5x40mm		Ø8x30mm	
H	X6	I	X3	J	X36	K	X2	M	X2	N	X2	O	X2
M4x18mm				M3.5x14mm		M4x35mm		M4x14mm		Ø6x30mm			
P	X12	Q	X4	R	X2								




1



O	x2
M	x2
A	x8

M4x14mm
M6x35mm


2






B	x8
G	x4


Ø15x9mm
Ø8x30mm

3




4




5

B	X6
	Ø15x9mm
A	X6
	M6x35mm

6

B	X14
	Ø15x9mm


7



C	x8

D	x8
	M3x14mm


8



N	x2
	Ø6x30mm


K	x2
	M4x35mm

9



P	x12

10



J	X12
M3.5x14mm	


Q	X4

R	X2

H	X6
M4x18mm	


I	X3

11



J	X8
	M3.5x14mm

12



J	X16
	M3.5x14mm

13

