



Thank you for purchasing this quality product. Be sure to unpack carefully looking for small parts which may have come loose during shipment.


Read all instruction and study the drawing carefully before starting the assembly process:

		HARDWARE PACK		
NO	DRAWING	DESCRIPTION	SIZE	Q'ty
A		BOLT	Φ 5/16″×1−1/2″	11pcs
В	\bigcirc	Flat Washer	Φ 5∕16∗Φ 19 ∗2″	11pcs
C	Ø	Lock Washer	Ф 5/16* Ф1 2*3″	11pcs
D	2	Wrench	12mm	1pc





STEP 3



STEP 4

D

В

