




PART LIST



A = 1 pc



B = 1 pc




C = 1 pc

LIST OF HARDWARE



NO.	Hardware	Qty.
1	Hex Bolts 	4 pcs
2	Plastic Washers 	8 pcs
3	Allen Wrench 	1 pc

Flying Square End Table

ASSEMBLY INSTRUCTIONS



Step 01



Step 02