

1. Carefully unpack and identify all parts referring to illustration for parts identification.
2. Turn power to the installation point OFF.
3. Unravel the fixture supply and ground wire and pass them through the center holes of nipple(F), cover(H), cap(I), hex nut(J), cap(K) and fixture loop(L).
4. Install the finial(A) into the metal ring(B), Carefully pass the center holes of cover(C), cap(D) and secure with the finial(E).
5. Thread nipple(F) into the coupler(G) as shown in the diagram, then pass the center holes of over(H), cap(I), hex nut(J) and cap(K) over nipple(F), and secure with fixture loop(L). Hands tighten until snug.
6. Install the candle sleeve(M) to each socket.
7. Install proper bulbs(not provided) to each socket referring to the markings and or labels on the fixture for maximum wattage.
8. Restore power to the installation point ON and retain this sheet for future reference.

