HTK-765-70E, LTK-765-70E, JTK-765-70E

WAC LIGHTING Responsible Lighting®

CAUTION:

For Use with WAC "H, L or J" track systems. Fixture may also be used on other manufacturers brand of track (consult factory for compatibility).

CAUTION – To reduce the risk of a burn during relamping, remove from the track before relamping. Read all instructions before installing.

FIXTURE INSTALLATION

- 1. Note the track has a groove running it's length to indicate polarity.
- 2. Insert adapter into track slot and rotate it 90°. The embossed arrow on the adapter should point to the grooved side of the track.
- 3. Push up and turn the locking tab into the lock position.
- 4. Removal is the reverse procedure. Tracks may be positioned anywhere along the track length.





RE-LAMPING:

- 1. Use appropriate protection when handling hot lamps.
- 2. Turn power off at main switch.
- 3. Unscrew lamp counterclockwise to remove.
- 4. Use Par 38 metal halide lamp 70W only.
- 5. Never operate a lamp that is chipped or damaged.
- 6. Installation is the reverse procedure.

Note: Metal halide lamps require several minutes of operation to reach full brightness. If power is interrupted lamps will take several minutes to re-strike. This is a normal characteristic of metal halide lamps.

Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050 **Western Distribution Center** 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585