## MAXIM

## Assembly Instruction For22291

1.Put the laser cut shade (N) on the metal cross framework (E), then make flat screw (C) through metal cross framework (E) and laser cut shade (N), then tighten round nut (L). 2.Put the fabric shade (P) on the metal cross framework (E), then tighten the ball nut (O) with flat screw (C). 3.Install the light bulb (W) into sucket. 4. Hang the crystal chains (A) on platform (K) 5.Hang the crystal chains (H).(G) on circle (J) 6.Hang the crystal chains (D).(B) on circle (I) 7 Hang the crystal chains (R).(M)

on circle (F)

