

60" x 32" Single-threshold shower base K-9164

## Features

- Safeguard<sup>®</sup> slip-resistant surface on bath floor.
- Single threshold for alcove installation with three tile-in flanges.
- Recessed drain (can be used with K-9155 or K-9156 drain cover).
- Right center drain.
- Ideal size for remodel installations into a 5-foot alcove with a shower door.
- Rim size optimized for water containment and aesthetics.

### Material

• KOHLER<sup>®</sup> enameled cast iron.

## **Required Products/Accessories**

K-9155 Drain Cover or K-9156 Drain Cover

## **Recommended Products/Accessories**

K-9132 Shower Drain K-23726 Drain treatment K-23725 Cast iron cleaner



## **Codes/Standards**

ASME A112.19.1/CSA B45.2 ASTM F462

# KOHLER<sup>®</sup> Enameled Cast Iron Bath and Shower Base Lifetime Limited Warranty

See website for detailed warranty information.

## **Available Colors/Finishes**

Color tiles intended for reference only.

| Color | Code | Description |
|-------|------|-------------|
|       | 0    | White       |
|       | 96   | Biscuit     |
|       | 47   | Almond      |
|       | NY   | Dune        |
|       | 95   | lce™ Grey   |
|       | G9   | Sandbar     |



# **Bellwether**®



60" x 32" Single-threshold shower base K-9164



## **Technical Information**

| All product dimensions are nominal. |                    |  |  |
|-------------------------------------|--------------------|--|--|
| Installation:                       | Three-wall alcove  |  |  |
| Drain location:                     | Right              |  |  |
| Weight:                             | 230 lbs (104.3 kg) |  |  |

#### Notes

Measure your actual product for rough-in details. Install this product according to the installation instructions.

The dimensions are applicable for this product only and should not be used to fabricate substitute bases for shower enclosures.

The K-1657/K-1663 or K-1708/K-1647-PC steam generator/control kit are designed for use with this product. Kohler Co. shall not be responsible for problems encountered due to the installation and use of other manufacturer's steam generators.

