













A  Φ 8*30 32pcs	B  2pcs	C  4pcs	D  Φ 3.5*14 42pcs	E  Φ 3.5*25 10pcs	F  5pcs	G  2pcs	H  4pcs	I  8pcs
J  4pcs	K  1pcs	L  4pcs						



1





A	$\Phi 8 \times 30$	D	$\Phi 3.5 \times 14$	I
				
16pcs		4pcs		4pcs

2




A	$\Phi 8 \times 30$	D	$\Phi 3.5 \times 14$	I	E	$\Phi 3.5 \times 25$	F
							
12pcs		4pcs		4pcs	10pcs		5pcs

3




4





Pay attention to the positive and negative poles


5





6




7




B  2pcs	C  4pcs	D Φ 3.5*14  26pcs	G  2pcs	H  4pcs
--	---	--	---	--

8




D Φ 3.5*14  8pcs	J  4pcs
--	--

9



10



Please remove the protective plastic film after the whole assemble process finished, then the surface will be high glossy, thank you for your choice