


# ASSEMBLY INSTRUCTION

WX16238

## COMPONENTS LIST


① Top x 1



⑤ Insert Nut x 8




② Side x 2




⑥ Plastic Hole Cover x 8



⑦ Wood Dowel x 4




③ Cross Bar x 2




④ 1½" Machine Screw x 8




## STEP 1



## STEP 2




## STEP 3




For missing parts or replacement , you may contact your merchant or its distribution center(Ph: 714-288-2005, Email:promanproducts@hotmail.com).  
For any other questions, please contact Customer Service Department of the merchant from where you placed your order.

STEP 4



STEP 5



Completed